


50 Cycle 3 Phase



Low Voltage

High Voltage

To Reverse Rotation, interchange
any two lines