




## Baldor Wiring Diagram for RP-2 through RP-8, single phase only.



### NOTES:

1. CONNECT LINE LEADS TO L1 AND L2.  
LOW VOLTAGE: CONNECT AS SHOWN.  
HIGH VOLTAGE: MOVE LEAD J TO TERM. 3.  
MOVE LEAD 2 TO TERM. 4.
2. CONNECTIONS ARE SHOWN FOR STANDARD ROTATION (CCW FACING END OPPOSITE SHAFT EXTENSION). INTERCHANGE LEADS 5 AND 8 TO REVERSE ROTATION.
3. MULTIPLE CAPACITORS ARE CONNECTED IN PARALLEL UNLESS OTHERWISE SPECIFIED.
4. LEAD COLORS ARE OPTIONAL. LEADS MUST ALWAYS BE NUMBERED AS SHOWN.

